



RECTANGULAR X-AXIS LRA
6X12mm
P/N: MHI-6440-S000


Outline drawing



Items	Conditions
Operating temperature Range	-20 Celsius ~ +60 Celsius -20℃~+60℃
Storage temperature Range	-30 Celsius ~ +70 Celsius -30℃~+70℃
Operating humidity Range	Humidity: 10~90%RH 10~90%RH。
Storage humidity Range	Humidity: 5~95%RH 5~95%RH
Measuring conditions	
Items	Conditions
Ambient temperature	20±5℃
Ambient humidity	65 RH±20%
Rated voltage	AC 2.0±0.05 Vrms Sine wave, 200Hz 
Input voltage range	AC 0~2.05 Vrms Sine wave
Measurement reference	Refer to the figure below to fix the vibrator and acceleration sensor, and then input the rated voltage for measurement 
Voltage-Acceleration Characteristics	